


[illegible]

RT-8		RT-324-EI					
TYPE	ASS'D. ON	TYPE	ASS'D. ON	TYPE	ASS'D. ON	TYPE	ASS'D. ON
ISSUE NO.	1 2 3 4						
MOD. NO.	396 298 396 396						
DATE	10-8-51 10-8-51 2-8-51 5-10-51						
DRAWN	JA JA JA JA						
CHECKED	JA JA JA JA						
PASSED	JA JA JA JA						
ISSUE NO.							
MOD. NO.							
DATE							
DRAWN							
CHECKED							
PASSED							

DEPARTMENT OF THE CHIEF MECHANICAL ENGINEER (ROAD SERVICES)
L. T. E. CHISWICK WORKS, LONDON, W.4.

PROCESS SPECIFICATION	TITLE	PART No
PT.6	REINFORCING PLATE - FRONT BOTTOM PANEL	RT.324.E2

30578 (4) (AUG. 1970 - C)	<p>ALTERATIONS</p> <p>ISSUE 2</p> <p>NOTE RE. MOD. 208 ADDED</p> <p>ISSUE 3</p> <p>3/4" DIA. HOLE BELIEVED TO BE FROM TOP OF PLATE WITH 4" DIM. NOTE, 45 HOLES 3/4" DIA. HOLE WAS 24 HOLES EXTREME OF 1/4" DIA. HOLE OF BOTTOM 4" GROUP. C5K WAS NOTE 4 HOLES - C5K WAS 2 HOLES NOTE THICKNESS WAS 1/8" NOW JARCE</p> <p>ISSUE 4</p> <p>HOLES OF COWL ARCH WAS 4 DIMS. WAS 1/8"</p>
------------------------------	---